

U.S. EPA REGION VIII TECHNICAL ENFORCEMENT PROGRAM RCRA COMPLIANCE EVALUATION INSPECTION REPORT

Facility:

Frontier Refining, Inc. 2700 East 5th Street

Cheyenne, WY 82007

Facility Contact:

David Weeks

Senior Project Engineer

EPA I.D. No.:

WYD051843613

Notification Status: LQG

Inspection Type:

Corrective Action Compliance Inspection

For Pond 2 Clean-Out

Date:

October 17, 2011

Time In:

3:00 p.m.

Time Out:

3:51 p.m.

EPA

Representatives:

Linda Jacobson, EPA Inspector

Philippe Pierre-Louis, EPA Inspector

Facility

Representatives:

David Weeks, Senior Project Engineer

Background:

Frontier Refining, Inc. operates a petroleum refinery in Cheyenne, Wyoming that produces asphalt, fuels, coke, and liquefied petroleum gas. On May 27, 2010, Frontier and EPA entered into a Consent Agreement to address the closure of Pond 2 surface impoundment. This inspection was prearranged and scheduled with facility representatives as a follow-up to observe the progress in waste removal, cleaning, and closure activities for the Pond 2 waste impoundment.

The EPA RCRA inspectors, Ms. Jacobson and Mr. Pierre-Louis, arrived at the facility at 3:00 pm and were greeted by Mr. David Weeks with Frontier's environmental department. Ms. Jacobson presented her credentials, explained the scope of the inspection, and completed the Notice of Inspection (NOI) Form. Entry was gained by consent as noted on the NOI form.

Physical Site Inspection

Mr. Weeks updated the inspectors on the progress of the Pond 2 work as they drove to the site of three pads which were being constructed for storage of clay and dirt. One pad was to be used for storage of contaminated clay, potentially a hazardous waste, the second for other clay material, and the third for dirt to be used for reconstruction of the Pond 2 footprint to serve as the tank base. These pads were to be lined with a semi-permeable liner.

The inspectors and facility representative arrived at the former Pond 2. Only the concrete apron on the north end was remaining. The facility had rinsed off the liner and removed the rinse water and other ponded water. Mr. Weeks stated that the existing synthetic liner will be cut up and put into roll-offs for proper disposal.

The inlet lines had been plugged. A continuing discharge, possibly groundwater, was still daylighting into the pond. The refinery was attempting to identify this water source and seal or remediate it.

Ms. Jacobson observed six drums of hazardous wastes removed from Pond 2 which were dated October 17, 2011 and labeled as "Pond 2 Sludge PPE Only".

The refinery had placed a 1000 gpm pump ahead of the API to pump water to Tank 121.

Closing Conference:

Ms. Jacobson completed the NOI form and held a short closing conference. No concerns were noted for the scope of the inspection conducted. Ms. Jacobson contacted Mr. Weeks with concern that a semi-permeable liner should not be used in the concrete pad used for the contaminated clay material which was potentially hazardous waste. He clarified that he had misspoken and that the liner would not allow seepage into the soils beneath the pad.

Prepared By:

Lindu Jawem Linda Jacobson, EPA Inspector November 16,2011 Date

Attachments:

Attachment 1: Notice of Inspection Form Attachment 2: Photographs and Photolog

ATTACHMENT 1 NOTICE OF INSPECTION FORM

U.S. ENVIRONMENTAL PROTECTION AGENCY (REGION VIII)

1595 Wynkocp Street, Denver, CO 80202

NOTICE OF INSPECTION

| Rescurce Conservation and Recovery Act (RCRA) Public Law 94-580, as amended. Toxic Substance Control Act (TSCA) Public Law 94-469, as amended. Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) Public Law 92-516, as amended. | | | | | | | | | | | |
|--|--------------------|----------------|-----------------------------|-------------|------------|------------------|--------|----------|----------|---------------|-------------|
| Date 10/14/11 | Inspector # | Daily Seq. | Hour In: 3:00 f | υ W 5332 | Facility | name | ter | Ref | بر ا | ふ、イト | C |
| Fac. Func. | Invest. Type | Reason | RCRA: Gen Transp. TSD | ii l | | | | | | B 61 5th S | |
| David | esentative(s) | Proje | | | P | | | 15 | 28 | 8 | · |
| Phone # (307)771-8827 Reason for Inspection: Entry by Consent: Warrant: () To determine the extent of compliance with the above referenced law, which may require the collection of samples, documents, and/or photographs. Other (Specify) Violations of above referenced law are suspected from information or complaint. Yes () No () | | | | | | | | | | | |
| Samples, Do | cuments, and /or F | hotos collecte | ed (describe b | elow) |) | | | | | Medium | Date to Lab |
| 2. 3. | 2 photos | | | | | | | | | | |
| 4. | | <u></u> | | | | | | | · - | | |
| 5. | | | | • | | | | | | | |
| 6. | | | | | | | | | | | |
| Samples requested and received by facility: 🔑 Yes ()No If yes:()Duplicate. ()Split. ()Photos (To be received when processed.) | | | | | | | | | | | |
| This inspection has revealed the following probably violations of EPA laws or regulations. No violations observed for scope of inspection conducted | | | | | | | | | | | |
| The facts established by this inspection will be reviewed by personnel in the EPA Regional Office. A final determination of your facility's compliance with EPA regulations will be made as a result of this review. The review may reveal additional violations. | | | | | | | | | | | |
| Receipt of th | e Notice of Inspec | tion is acknow | rledged. | Signa | ature of L | n de .ead Ins | pector | المدينة | <u>~</u> | | |
| Signature of | And Land | tive | | Assis | sting Insp | ectors (| EPAT | ribe/Sta | ite) | | |
| į į | V | | | | | | | | | | |

ATTACHMENT 2 PHOTOLOG AND PHOTOGRAPHS

PHOTOLOG FOR FRONTIER REFINING INSPECTION

| РНОТО | SUBJECT | DATE |
|-------|--|------------------|
| 1 | One of Three Storage Pads Being Constructed Of Pond 2 Spoils | October 17, 2011 |
| 2 | Storage Pad for Pond 2 Excavated Materials | October 17, 2011 |
| 3 | Pond 2 with Portion of Concrete Apron Removed | October 17, 2011 |
| 4 | Inlet Piping Plugged for Liner Removal Work | October 17, 2011 |
| 5 | Areas of Ponded Water to Be Removed by | October 17, 2011 |
| | Vacuum Truck | • |
| 6 | Continuing Inflow of Water, Possibly Groundwater | October 17, 2011 |
| 7 | Location of Water Seep | October 17, 2011 |
| 8 | Pond 2 Prior to Synthetic Liner Being Pulled | October 17, 2011 |
| 9 | Water Flow into Pond 2, Possibly Groundwater | October 17, 2011 |
| 10 | Status of Pond 2 | October 17, 2011 |
| 11 | Pond 2 Liner to Be Removed | October 17, 2011 |
| 12 | Water Seep, Clear Constant Stream of Water Uncovered | October 17, 2011 |

Facility: Frontier Refining

Subject: One of Three Storage Pads Being Constructed for Pond 2 Spoils

Photographer: Linda Jacobson

Date: October 17, 2011



Photo: 2

Facility: Frontier Refining

Subject: Storage Pad for Pond 2

Excavated Materials

Photographer: Linda Jacobson



Facility: Frontier Refining

Subject: Pond 2 with Portion of

Concrete Apron Removed

Photographer: Linda Jacobson

Date: October 17, 2011




Photo: 4

Facility: Frontier Refining

Subject: Inlet Piping Plugged for

Liner Removal Work

Photographer: Linda Jacobson



Facility: Frontier Refining

Subject: Areas of Ponded Water to Be Removed by Vacuum Truck Photographer: Linda Jacobson

Date: October 17, 2011



Photo: 6

Facility: Frontier Refining

Subject: Continuing Inflow of Water,

Possibly Groundwater

Photographer: Linda Jacobson



Facility: Frontier Refining

Subject: Location of Water Seep Photographer: Linda Jacobson

Date: October 17, 2011



Photo: 8

Facility: Frontier Refining
Subject: Pond 2 Prior to
Synthetic Liner Being Pulled
Photographer: Linda Jacobson



Facility: Frontier Refining

Subject: Water Flow into Pond 2,

Possibly Groundwater

Photographer: Linda Jacobson

Date: October 17, 2011



Photo: 10

Facility: Frontier Refining Subject: Status of Pond 2

Photographer: Linda Jacobson





Facility: Frontier Refining

Subject: Pond 2 Liner to Be Removed

Photographer: Linda Jacobson

Date: October 17, 2011



Photo: 12

Facility: Frontier Refining

Subject: Water Seep, Clear Constant

Stream of Water Uncovered

Photographer: Linda Jacobson

